

# *Lead Inspection Report*

FOR THE PROPERTY LOCATED AT:

**14616 Pennsylvania Avenue  
Hagerstown, MD**

Prepared For:  
**Triad Engineering  
Patrick Upham  
1075-D Sherman Ave.  
Hagerstown, MD 21740**

Report Prepared and Submitted by:


**Jason A. Young**  
*Jason A. Young / WV Risk Assessor – License # MD 17151*  
**Baxter Environmental Group, Inc.  
941 Progress Road  
Chambersburg, PA 17201  
Phone: 717-263-7341**

Date of Inspection:  
**12/1/2022**

**BAXTER  
ENVIRONMENTAL  
GROUP, INC.**

**941 Progress Road Chambersburg, PA 17201**  
**baxtergroupinc.com**  
Phone 717-263-7341 | Toll Free 800-990-7210  
Fax 717-263-7941 | Email [info@baxtergroupinc.com](mailto:info@baxtergroupinc.com)

# BAXTER ENVIRONMENTAL GROUP, INC.



941 Progress Road, Chambersburg, PA 17201

Office: 717-263-7341

Fax: 717-263-7941

[www.baxtergroupinc.com](http://www.baxtergroupinc.com)

[info@baxtergroupinc.com](mailto:info@baxtergroupinc.com)

December 6, 2022

Triad Engineering  
Attn: Patrick Upham  
1075-D Sherman Ave.  
Hagerstown, MD 21740

**RE: *Limited Lead-Based Paint Risk Assessment  
14616 Pennsylvania Ave., Hagerstown, MD.***

Dear Mr. Upham:

The purpose of the limited lead-based paint risk assessment was to determine the existence of lead-based paint and lead-based paint hazards associated with 14616 Pennsylvania Avenue, Hagerstown, MD and to determine the location, type, and severity of existing or potential health hazards associated with exposures to lead during a possible demolition of the property. This report can assist you in developing a plan for eliminating any lead-based paint hazards that were found and aid in establishing an ongoing lead-based paint maintenance and re-evaluation program, if needed.

As part of the assessment, a visual survey was conducted. On-site paint testing using an x-ray fluorescence (XRF) analyzer was performed on the surfaces. Note that readings were limited. Building components with similar paint histories are to be assumed to have similar readings.

The risk assessment was conducted on two (2) buildings located on the property, the main house, and the garage.

The State of Maryland considers any reading greater than  $0.7 \mu\text{g./cm}^2$  to be lead-based paint. OSHA considers any level of lead to lead containing and lead safe practices should be followed.

Both buildings were found to have some components that do contain lead-based paint.

If the buildings are demoed, the waste from these buildings would need to have TCLP analysis performed to assure of proper disposal.

The areas that contain lead-based paint are as follows:

## **Garage**

- The person door
- The window components

## House

- Exterior wood window components
- Exterior wood door components
- Wood Siding, may be under the metal siding as well
- Plaster wall (A) of the kitchen
- Yellow plaster walls and ceiling in Bedroom 2
- The former exterior wood components of the back porch

### Health Effects of Lead Exposure:

Lead is a soft metal, naturally occurring in the Earth's crust. It has been determined, however, that lead has no useful purpose in the human body and acts as a toxin. It takes the place of essential minerals such as calcium, potassium, and iron, which are vital to the construction and repair of bones, organs and blood. Lead exposures are a major health concern, especially in young children under the age of six.

Children, due to their smaller body mass and higher metabolism, are affected by lead exposures much more severely than adults. They ingest lead through daily hand-to-mouth activities and may develop severe attention deficit disorders, irreversible brain injury, learning disabilities and aggressive behaviors.

The documentation within this report details the results of the limited XRF inspection for risk assessment. Please consult the appendix for additional information on how to interpret XRF results, definitions of terms, measurement standards, site and floor plans, the U.S. Environmental Protection Agency (EPA) brochure entitled "Protect Your Family from Lead in Your Home", and associated pictures.

If this property is not renovated to become lead-free, a copy of this report must be provided to any purchaser of this property under Federal law (24 CFR part 35 and 40 CFR part 745) before they become obligated under sales contract. Sellers are also required to distribute the educational pamphlet approved by the U.S. Environmental Protection Agency (EPA), entitled "Protect Your Family from Lead in Your Home", and include standard warning language in their sales contracts to ensure that parents have the information they need to protect their children from lead-based paint hazards.

If these properties are to be rented, a copy of this report must be provided to each new tenant before taking possession of the property. All lead-based painted surfaces must be intact prior to taking possession of the property and should be inspected every two years by the landlord. For more information regarding your obligations under federal lead-based paint regulations, contact 800-424-LEAD (5323).

Regards,

  
Jason Young  
MD Risk Assessor License #17151

Enclosures

### Baxter Group, Inc.


PA HIC Number: PA023563 • MHIC Number: 05-130104 • WV Number: WV029674  
www.baxtergroupinc.com • info@baxtergroupinc.com

Company Heuresis Corp.  
 Model Pb200i  
 Type XRF Lead Paint Analyzer  
 Serial Num. 1776  
 App Version Pb200i-4.1-11

14616 Pennsylvania Ave., Hagerstown, MD

Reading #	Concentration	Units	Result	Action Level	Date	Time	Room	Side	Structure	Component	Substrate	Color	Condition
1	1	mg/cm2	POS	0.7	12/1/2022	8:54:27	Calibration						
2	1	mg/cm2	POS	0.7	12/1/2022	8:54:42	Calibration						
3	1.1	mg/cm2	POS	0.7	12/1/2022	8:55:01	Calibration						
4	0	mg/cm2	NEG	0.7	12/1/2022	8:56:53	Garage	A	Door	Casing	Wood	White	Peeling
5	0.1	mg/cm2	NEG	0.7	12/1/2022	8:57:33	Garage	A	Wall		Wood	White	Peeling
6	2	mg/cm2	POS	0.7	12/1/2022	8:57:56	Garage	A	Door		Wood	White	Peeling
7	0.1	mg/cm2	NEG	0.7	12/1/2022	8:58:20	Garage	A	Door	Jamb	Wood	White	Peeling
8	6.3	mg/cm2	POS	0.7	12/1/2022	8:59:46	Garage	D	Window	Sash	Wood	White	Peeling
9	7	mg/cm2	POS	0.7	12/1/2022	9:00:13	Garage	D	Window	Stool	Wood	White	Peeling
10	7.9	mg/cm2	POS	0.7	12/1/2022	9:03:01	Garage	D	Window		Wood	White	Peeling
11	6.2	mg/cm2	POS	0.7	12/1/2022	9:03:21	Outside of House	A	Door	Casing	Wood	White	Peeling
12	6.1	mg/cm2	POS	0.7	12/1/2022	9:03:37	Outside of House	A	Door	Jamb	Wood	White	Peeling
13	6.1	mg/cm2	POS	0.7	12/1/2022	9:04:18	Outside of House	A	Door	Casing	Wood	White	Peeling
14	7.5	mg/cm2	POS	0.7	12/1/2022	9:05:07	Outside of House	A	Window	Casing	Wood	White	Peeling
15	9.8	mg/cm2	POS	0.7	12/1/2022	9:05:26	Outside of House	A	Window	Casing	Wood	White	Peeling
16	9.8	mg/cm2	POS	0.7	12/1/2022	9:06:27	Outside of House	A	Window	Sash	Wood	White	Peeling
17	7.6	mg/cm2	POS	0.7	12/1/2022	9:06:45	Outside of House	B	Door		Wood	White	Peeling
18	0.3	mg/cm2	NEG	0.7	12/1/2022	9:07:45	Outside of House	B	Shutter	Casing	Wood	White	Peeling
19	0.2	mg/cm2	NEG	0.7	12/1/2022	9:08:24	Outside of House	B	Post		Metal	Black	Intact
20	7.7	mg/cm2	POS	0.7	12/1/2022	9:09:26	Outside of House	C	Door		Wood	White	Peeling
21	8.3	mg/cm2	POS	0.7	12/1/2022	9:09:45	Outside of House	C	Door		Wood	White	Peeling
22	9.1	mg/cm2	POS	0.7	12/1/2022	9:11:00	Outside of House	C	Wall		Wood	Beige	Peeling
23	0	mg/cm2	NEG	0.7	12/1/2022	9:11:56	Outside of House	C	Foundation		Cement	Green	Peeling
24	0.7	mg/cm2	POS	0.7	12/1/2022	10:10:05	Kitchen	A	Wall		Plaster	White	Peeling
25	0.2	mg/cm2	NEG	0.7	12/1/2022	10:11:10	Kitchen	A	Wall	Baseboard	Wood	White	Peeling
26	0.1	mg/cm2	NEG	0.7	12/1/2022	10:11:34	Kitchen	A	Door	Casing	Wood	White	Peeling
27	0.5	mg/cm2	NEG	0.7	12/1/2022	10:11:58	Kitchen	B	Wall		Plaster	White	Peeling
28	0.1	mg/cm2	NEG	0.7	12/1/2022	10:12:35	Kitchen	B	Door	Casing	Wood	White	Peeling
29	0.3	mg/cm2	NEG	0.7	12/1/2022	10:13:01	Kitchen	C	Door		Wood	White	Peeling
30	0.2	mg/cm2	NEG	0.7	12/1/2022	10:13:41	Kitchen	C	Window	Casing	Wood	White	Peeling
31	0.1	mg/cm2	NEG	0.7	12/1/2022	10:14:02	Kitchen	D	Window	Casing	Wood	White	Peeling
32	0.8	mg/cm2	POS	0.7	12/1/2022	10:14:38	Kitchen	Ceiling	Wall		Plaster	White	Peeling
33	0.3	mg/cm2	NEG	0.7	12/1/2022	10:15:57	Dining Room	A	Wall		Plaster	Beige	Peeling
34	0.1	mg/cm2	NEG	0.7	12/1/2022	10:16:21	Dining Room	A	Wall	Baseboard	Wood	Beige	Peeling
35	0.1	mg/cm2	NEG	0.7	12/1/2022	10:16:47	Dining Room	A	Window	Stool	Wood	Beige	Peeling
36	0.3	mg/cm2	NEG	0.7	12/1/2022	10:17:16	Dining Room	B	Wall		Plaster	Beige	Peeling
37	0.4	mg/cm2	NEG	0.7	12/1/2022	10:18:04	Dining Room	Ceiling	Wall		Plaster	Beige	Peeling
38	0.5	mg/cm2	NEG	0.7	12/1/2022	10:18:51	Living Room	A	Wall		Plaster	Beige	Peeling
39	0.1	mg/cm2	NEG	0.7	12/1/2022	10:19:33	Living Room	A	Window	Casing	Wood	Beige	Peeling
40	0.1	mg/cm2	NEG	0.7	12/1/2022	10:19:54	Living Room	A	Window	Stool	Wood	Beige	Peeling
41	0.3	mg/cm2	NEG	0.7	12/1/2022	10:20:23	Living Room	C	Door		Wood	White	Peeling
42	0.2	mg/cm2	NEG	0.7	12/1/2022	10:20:39	Living Room	C	Door	Casing	Wood	White	Peeling
43	0.1	mg/cm2	NEG	0.7	12/1/2022	10:21:21	Living Room	C	Wall	Fire Place Mantle	Wood	White	Peeling
44	0.3	mg/cm2	NEG	0.7	12/1/2022	10:22:01	Living Room	C	Window	Casing	Wood	White	Peeling

45	0.4	mg/cm2	NEG	0.7	12/1/2022	10:22:31	Living Room	C	Wall	Plaster	Beige	Peeling
46	0.3	mg/cm2	NEG	0.7	12/1/2022	10:23:44	Foyer	A	Wall	Plaster	Beige	Peeling
47	0.2	mg/cm2	NEG	0.7	12/1/2022	10:24:10	Foyer	A	Wall	Wood	Beige	Peeling
48	0.1	mg/cm2	NEG	0.7	12/1/2022	10:24:34	Foyer	A	Door	Wood	Beige	Intact
49	0.1	mg/cm2	NEG	0.7	12/1/2022	10:24:50	Foyer	A	Door	Wood	Beige	Intact
50	0.3	mg/cm2	NEG	0.7	12/1/2022	10:25:18	Foyer	B	Wall	Plaster	Beige	Intact
51	0	mg/cm2	NEG	0.7	12/1/2022	10:25:52	Foyer	B	Stairwell	Wood	White	Intact
52	0.2	mg/cm2	NEG	0.7	12/1/2022	10:26:15	Foyer	B	Stairwell	Wood	White	Intact
53	0.1	mg/cm2	NEG	0.7	12/1/2022	10:26:33	Foyer	B	Stairwell	Wood	White	Intact
54	0.2	mg/cm2	NEG	0.7	12/1/2022	10:26:59	Foyer	C	Stairwell	Wood	White	Intact
55	0.4	mg/cm2	NEG	0.7	12/1/2022	10:45:40	Foyer	C	Stairwell	Wood	White	Intact
56	0	mg/cm2	NEG	0.7	12/1/2022	10:46:17	Bedroom 1	A	Wall	Plaster	White	Intact
57	0.2	mg/cm2	NEG	0.7	12/1/2022	10:46:41	Bedroom 1	A	Wall	Wood	White	Intact
58	0.1	mg/cm2	NEG	0.7	12/1/2022	10:47:20	Bedroom 1	A	Window	Wood	White	Intact
59	0	mg/cm2	NEG	0.7	12/1/2022	10:47:46	Bedroom 1	B	Wall	Plaster	White	Intact
60	0	mg/cm2	NEG	0.7	12/1/2022	10:48:06	Bedroom 1	B	Wall	Wood	White	Intact
61	0.2	mg/cm2	NEG	0.7	12/1/2022	10:48:34	Bedroom 1	B	Closet Door	Wood	White	Intact
62	0.8	mg/cm2	POS	0.7	12/1/2022	10:49:12	Bedroom 2	B	Closet Door Jamb	Wood	White	Intact
63	0.1	mg/cm2	NEG	0.7	12/1/2022	10:50:15	Bedroom 2	B	Door	Plaster	Yellow	Peeling
64	0	mg/cm2	NEG	0.7	12/1/2022	10:50:40	Bedroom 2	B	Wall	Wood	White	Peeling
65	0.8	mg/cm2	POS	0.7	12/1/2022	10:51:12	Bedroom 2	C	Window	Wood	White	Peeling
66	0.1	mg/cm2	NEG	0.7	12/1/2022	10:51:52	Bedroom 2	D	Wall	Plaster	Yellow	Peeling
67	0.1	mg/cm2	NEG	0.7	12/1/2022	10:52:08	Bedroom 2	D	Door	Wood	White	Peeling
68	0.7	mg/cm2	POS	0.7	12/1/2022	10:52:37	Bedroom 2	Ceiling	Door	Wood	White	Peeling
69	0.2	mg/cm2	NEG	0.7	12/1/2022	10:53:24	Bathroom	Ceiling	Wall	Plaster	Yellow	Peeling
70	0.4	mg/cm2	NEG	0.7	12/1/2022	10:53:46	Bathroom	B	Wall	Plaster	White	Peeling
71	0.2	mg/cm2	NEG	0.7	12/1/2022	10:54:14	Bathroom	D	Wall	Plaster	White	Peeling
72	0.1	mg/cm2	NEG	0.7	12/1/2022	10:54:31	Bathroom	D	Door	Wood	White	Peeling
73	0.4	mg/cm2	NEG	0.7	12/1/2022	10:55:03	Bathroom	A	Door	Wood	White	Peeling
74	-0.1	mg/cm2	NEG	0.7	12/1/2022	10:55:39	Bedroom 3	A	Wall	Plaster	White	Peeling
75	0	mg/cm2	NEG	0.7	12/1/2022	10:55:58	Bedroom 3	A	Wall	Wood	White	Intact
76	0.1	mg/cm2	NEG	0.7	12/1/2022	10:56:15	Bedroom 3	B	Wall	Wood	White	Intact
77	0	mg/cm2	NEG	0.7	12/1/2022	10:56:36	Bedroom 3	B	Door	Wood	White	Intact
78	0.2	mg/cm2	NEG	0.7	12/1/2022	10:57:01	Bedroom 3	C	Door	Wood	White	Intact
79	0.4	mg/cm2	NEG	0.7	12/1/2022	10:57:47	Hallway	A	Window	Wood	White	Intact
80	0.1	mg/cm2	NEG	0.7	12/1/2022	10:58:14	Hallway	D	Closet Door	Wood	White	Intact
81	0	mg/cm2	NEG	0.7	12/1/2022	10:58:44	Hallway	A	Wall	Plaster	Beige	Intact
82	0.1	mg/cm2	NEG	0.7	12/1/2022	10:59:01	Hallway	C	Wall	Plaster	Beige	Intact
83	0.2	mg/cm2	NEG	0.7	12/1/2022	10:59:41	Hallway	C	Wall	Wood	White	Intact
84	7.9	mg/cm2	POS	0.7	12/1/2022	11:00:36	Stairwell	C	Closet Door Jamb	Wood	White	Peeling
85	7.6	mg/cm2	POS	0.7	12/1/2022	11:00:58	Back Porch	A	Window	Wood	Beige	Peeling
86	0.9	mg/cm2	POS	0.7	12/1/2022	11:01:24	Back Porch	A	Window	Wood	Beige	Peeling
87	0	mg/cm2	NEG	0.7	12/1/2022	11:02:17	Back Porch	Ceiling	Wall	Wood	Beige	Peeling
88	1	mg/cm2	POS	0.7	12/1/2022	11:03:35	Calibration	C	Window	Wood	Beige	Peeling
89	1	mg/cm2	POS	0.7	12/1/2022	11:03:56	Calibration	C	Window	Wood	Beige	Peeling
90	0.9	mg/cm2	POS	0.7	12/1/2022	11:04:16	Calibration	C	Window	Wood	Beige	Peeling



A  
14616 PENNSYLVANIA AVE  
SCOTTSDALE, ARIZONA

D

BR3

BR1

HALL


BATH

C



BR2

B


GARAGE




BASMENT



14616 PENNSYLVANIA AVE  
1ST FLOOR



Garage People Door and Window Components



Wooden Door Components



Wood Door Components



Wood Window Components, possibly under wrap



Wood Basement Window Components




Wood Door Components




Wood Door Components



Wood Siding, possibly under wrap as well



Kitchen Wall A



Bedroom 2 Walls




Back Porch Wood Window Components, Wall Side and Ceiling

**THIS IS TO CERTIFY THAT**

**Jason Allen Young**

**HAS MET THE LEAD PAINT SERVICES  
ACCREDITATION REQUIREMENTS FOR**




**TRAINING PROVIDER: Aerosol Monitoring & Analysis, Inc.**

**COURSE DATE: 02/15/2021**

**Certificate # 17151**

**09/06/2022**  
Date

  
**ADMINISTRATOR, LEAD PAINT ACCREDITATION  
MARYLAND DEPARTMENT OF THE ENVIRONMENT**

**STATE OF MARYLAND**